



Applies To: **ALL Models**

February 9, 1998

1998 Honda Paint Codes

(Supersedes 97-083, dated December 15, 1997)

Paint formulations are determined by each paint company. For questions about formulas or matching, contact your local paint company's nearest regional office. American Honda does not endorse any paint company or type of paint; this information is provided for reference only.

The original paint is acrylic enamel. Paint codes with "M" are metallic colors; those with "P" are pearlescent colors.

NOTE: *Herberts Stadox* uses the Honda Paint Code as its paint intermix code.

CG Marysville, Ohio-produced cars (VIN: 1HGCF_____WA_____)

PAINT CODE	COLOR	MODEL	DUPONT	PPG	BASF	SHERWIN-WILLIAMS Martin Senour	SIKKENS (Add "HON" prefix to each number)	ICI AUTOCOLOR	SPIES-HECKER	HONDA TOUCH-UP P/N (Add "08703-" pre- fix to each number)
B80P	Mystic Blue ¹	ACC	F2682	5341	27202	54539	9181	JBW3B	80692	B80PAH
G87P	Dark Emerald ¹	ACC	F3774	5458	28122	56637	9226	LPL3B	65240	G87PPAA
NH578	Taffeta White ³	ACC	F4114	5461	28185	56724	4006	LPK9B	22220	NH578AH
NH592P	Flamenco Black P ¹	ACC	F3071	9939	26309	53032	9141	EMK5B	73185	NH592PAH
NH612M	Regent Silver M ¹	ACC	F4115	5460	28123	56636	9228	LPL1B	74346	NH612MA
R94	San Marino Red	ACC	F2683	5389	27203	54543	3007	JHC8B	33552	R94AH
RP25P	Black Currant P ¹	ACC	F2681	5390	27204	54541	9183	JHC9B	40687	RP25PAH
RP29P	Raisin Pearl ¹	ACC	F5011	5459	28124	56638	9227	LPL2B	40951	RP29PAA
YR508M	Heather Mist ¹	ACC	F1696	5031	26311	53035	9142	EMK3B	73186	YR508MAH

East Liberty, Ohio-produced cars (VIN: 1HGEJ_____WL_____)

(These are waterborne colors with a solvent borne clear coat.)

PAINT CODE	COLOR	MODEL	DUPONT	PPG	BASF	SHERWIN-WILLIAMS Martin Senour	SIKKENS (Add "HON" prefix to each number)	ICI AUTOCOLOR	SPIES-HECKER	HONDA TOUCH-UP P/N (Add "08703-" pre- fix to each number)
B73M	Cyclone Blue M ¹	CIV	F1692	5165	26282	53016	9148	BGG1B	54503	B73MPAH
G82P	Cypress Green P ¹	CIV	F1694	5187	26284	53017	9149	BHE9B	62037	G82PPAH
NH578	Taffeta White ¹	CIV	F5009	5465	28187	56726	4006	LTJ7B	22222	NH578AH
NH583M	Vogue Silver M ¹	CIV	F1695	5033	26281	53015	9150	BHF1B	73111	NH583MAH
NH592P	Flamenco Black P ¹	CIV	F2434	5280	27093	54013	9141	GEA2B	74345	NH592PAH
R81	Milano Red, Base ²	CIV	H9817	4779	23424	48115	3000	6GS5B	30372	R81PPAH
	Milano Red, Top ²		W9951	4781						
R96P	Inza Red P ¹	CIV	F2398	5283	27062	54014	9176	GHX1B	33556	R96PPAH

- NOTES: The numbers following the paint description represent the paint process used during manufacture of the vehicle:
- ¹ Two-stage process, a clear coat is applied over the color coat.
 - ² A small amount of color is mixed with a clear coat and applied over the color coat (two-stage process with tinted clear).
 - ³ No clear coat was applied (single stage process).

Index # 049681

CUSTOMER INFORMATION: The information in this bulletin is intended for use *only* by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by "do-it-yourselfers," and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Honda automobile dealer.

Suzuka, Japan-produced cars (VIN: JHMEJ_____WS_____)

PAINT CODE	COLOR	MODEL	DUPONT	PPG	BASF	SHERWIN-WILLIAMS Martin Senour	SIKKENS (Add "HON" prefix to each number)	ICI AUTOCOLOR	SPIES-HECKER	HONDA TOUCH-UP P/N (Add "08703-" pre- fix to each number)
B-73M	Cyclone Blue ¹	CIV	F1812	5430	26305	56721	9114	ARV7B	54398	B73MPAH
G-82P	Cypress Green P ¹	CIV	F1810	5202	26306	53031	9115	ARW3B	61935	G82PPAH
NH-578	Taffeta White ³	CIV	W9982	4876	24285	56724	4002	5PK3B	10674	NH578AH
NH-583M	Vogue Silver M ¹	CIV	F1070	5033	25241	51145	9084	6WR8B	72206	NH583MAH
NH-592P	Flamenco Black P ¹	CIV	F1686	5203	26279	54571	9129	9JM3B	73014	NH592PAH

Sayama, Japan-produced cars (VIN: JHMRA_____WC_____)
BB
RD

PAINT CODE	COLOR	MODEL	DUPONT	PPG	BASF	SHERWIN-WILLIAMS Martin Senour	SIKKENS (Add "HON" prefix to each number)	ICI AUTOCOLOR	SPIES-HECKER	HONDA TOUCH-UP P/N (Add "08703-" pre- fix to each number)
B-80P	Mystic Blue P ¹	ODD	F2733	5337	27195	54538	9179	JCC5B	55099	B80PAH
B-83M	Nordic Mist M ¹	PRE	F2734	5340	27196	54542	9196	HVT6B	55101	B83MAH
B-84P	Supermarine Blue ¹	CR-V	F2731	5319	27197	54545	9177	HNL1B	55102	B84PPAH
B-91M	Crystal Blue M ¹	ODD	F4102	5456	28184	56722	9225	LPK8B	56290	B91MMAA
G-82P	Cypress Green P ¹	CR-V	F1810	5202	26306	54825	9115	ARW3B	61935	G82PPAH
G-83P	Eucalyptus Green P ¹	ODD, PRE	F1684	5191	26307	52870	9131	9JM5B	61936	G83PPAH
NH-552M	Sebring Silver ¹	CR-V	W9375	4362	27199	44893	9425	2781B	98986	NH552MAH
NH-578	Taffeta White ³	ODD	W9982	4876	24285	49558	4002	5PK3B	10674	NH578AH
NH-592P	Flamenco Black P ¹	PRE, CR-V	F1686	5203	26279	52869	9129	9JM3B	73014	NH592PPA
NH-603P	White Diamond Base	PRE	F3073	5428	28189	56728	9197	JGG5G	19727	NH603PPA
	White Diamond Top		F3043	5429		56729		JGG4B	19724	NH603PAH
R-94	San Marino Red	PRE, CR-V	F1687	5348	27210	52949	3003	9JMGB	33138	R94AH
RP-25P	Black Currant P ¹	ODD	F1682	5200	26314	52871	9132	9JM7B	40543	RP25PAH
YR-508M	Heather Mist ¹	ODD	F0906	5031	25246	51151	9095	7BB7B	72289	YR508MAH

NOTES:

The numbers following the paint description represent the paint process used during manufacture of the vehicle:

- ¹ Two-stage process, a clear coat is applied over the color coat.
- ² A small amount of color is mixed with a clear coat and applied over the color coat (two-stage process with tinted clear).
- ³ No clear coat was applied (single stage process).

Alliston, Canada-produced cars (-4) (VIN: 2HGEJ_____WH_____)

PAINT CODE	COLOR	MODEL	DUPONT	PPG	BASF	SHERWIN-WILLIAMS Martin Senour	SIKKENS (Add "HON" prefix to each number)	ICI AUTOCOLOR	SPIES-HECKER	HONDA TOUCH-UP P/N (Add "08703-" pre- fix to each number)
B-73M-4	Cyclone Blue M ¹	CIV	F1631	5163	26278	52925	9152	BHF2B	54502	B73MPAH
G-82P-4	Cypress Green P ¹	CIV	F1629	5172	26277	52924	9143	BGGZB	62036	G82PPAH
NH-578-4	Taffeta White ³	CIV	F4146	91752	28186	56725	4007	LTK8B	22221	NH578AH
NH-583M-4	Vogue Silver M ¹	CIV	F2027	5190	26280	52922	9145	BFV2B	73112	NH583MAH
NH-592P-4	Flamenco Black P ¹	CIV	F4147	95132	28188	56727	9230	LTK9B	74344	NH592PAH
PB-74P-4	Dark Amethyst P ¹	CIV	F2313	5338	27200	54544	9184	JCC6B	40688	PB74PAH
R-96P-4	Inza Red P ¹	CIV	F3029	75254	27205	54586	9185	JHC7B	33555	R96PPAH
R-97-4	Roma Red (tnt clr) ²	CIV	F1852	5204	26276	52923	3005	BFV3B	33197	R97PPAH

'98 Passport Color Codes (VIN: 4S6CM_____W4_____)

(These are waterborne colors with a solvent borne clear coat.)

PAINT CODE	COLOR	DUPONT	PPG	BASF	SHERWIN-WILLIAMS Martin Senour	SIKKENS (Add "HON" prefix to each number)	ICI AUTOCOLOR	SPIES-HECKER	HONDA TOUCH-UP P/N (Add "08703-" pre- fix to each number)
731/R409	Claret Red P ¹	F0428	74090	24452	49178	9073	SWY8B	32841	DR3452
752/W101	Cream White ¹	F0422	4526	24454	46030	4003	TG62B	12101	WH3472
715/G103	Huntsman Green MIC ¹	N9570	4517	26312	54122	9134	PK55B	62123	HG1032
826/001	Ebony Black ¹	F0426	9829	24457	33756	4004	TE91B	72611	BK3502
835/N818	Bright Silver ¹	F3175	36400	28099	57003	9233	IJF2B	74564	N818AH

'98 Honda Electric Cars (VIN: JHMZA_____WT_____)

(All EVs are two tone)

PAINT CODE	COLOR	DUPONT	PPG	BASF	SHERWIN-WILLIAMS Martin Senour	SIKKENS (Add "HON" prefix to each number)	ICI AUTOCOLOR	SPIES-HECKER	HONDA TOUCH-UP P/N (Add "08703-" pre- fix to each number)
Silver NH-552M NH-613M	Sebring Silver ¹ Mineral Grey ¹	W9375 F4157	4362 36574	27199 28279	44893 56521	9425 9215	2781B KML1B	98986 74210	NH522MAH NH613MAH
Green G-88P G-89P	Emerald Mist ¹ Sequoia Green ¹	F4154 F4153	48464 48463	28280 28281	56523 56522	9216 9217	KML2B KML3B	65057 65058	G88PPAH G89PPAH
Beige YR-516M YR-517P	Moonlight Beige ¹ Nutmeg Brown ¹	F4155 F4156	28655 28656	28282 28283	56520 56516	9218 9219	KML5B KML6B	22042 81590	YR16MAH YR517PAH

NOTES:

The numbers following the paint description represent the paint process used during manufacture of the vehicle:

- ¹ Two-stage process, a clear coat is applied over the color coat.
- ² A small amount of color is mixed with a clear coat and applied over the color coat (two-stage process with tinted clear).
- ³ No clear coat was applied (single stage process).